

Cl/SfB 125	(2-)	(W7)
Common Arrangement C40/J30/J31/P22		

Project: Onsite Renovation
Title: Casa Caribe, Cancun, Mexico
Date: June 2002

This stunning property has a front view of the beach; all the glass can be moved so the living room integrates with the beach and the Caribbean Sea. The glass is a fundamental part of the design of the house.

However, after several years of exposure to Cancun's weather, it started to become harder to clean and more importantly the time it stayed clean began to shorten. This obviously increased the frequency and costs of cleaning. It got to the stage where it had to be cleaned every day – even on occasion, several times a day in order to have the crystal clear view the owner demanded.



Before renovation



After renovation

The specialised process of stain removal is part of a unique renovation process, which prepares and allows for the ClearShield protection to be applied. After the ClearShield application – fantastic results have been achieved.

The cleaning of the ClearShield 'non-stick' Glass now only takes place twice a week with very little effort involved, saving costs. The owner of the house can now appreciate a perfect view and the beautiful appearance of the glass is preserved.